

Safety Relief Valve Parts Reference Manual REVISION SHEET

Revisions made to this instruction are listed in detail and chronological order.

DATE	REV. NO.	DESCRIPTION
12/16/02	1	Section 5a, page 7 – Corrected Disc holder material description to state 316 SS, was Inconel X750. Section 1, page 27 – Changed RF Nozzle part number for 1912/14/16H to 0590003. Part was incorrectly listed as 0590003.
3/7/03	2	Section 5b, page 6 – Corrected Disc holder part number for 19226M, was 4840895.
3/26/03	3	Section 7, page 3 – Corrected Adjusting Ring Pin Gasket part number for 1 ½" 1982, was 3620112.
3/27/03	4	Section 4, page 30 – Corrected Spindle part number for 1905K Conventional - P3. Part was listed as 1985501.
4/11/03	5	Section 1, page 40 – Class II Parts, R.F. Nozzle: Added part numbers for 1914M. Section 1, page 8 – Corrected part number for RJ Nozzle 1914/16D, was 4790405.
5/15/03	6	Section 5a, page 8 – Changed Base-MNPT & Base-FNPT part numbers for all sizes. Section 4, page 14 – Nozzle Raised Face, moved the dividing line to be between the 1916 & 1918.
3/20/04	7	Section 1, page 23 – Inserted RJ Nozzle part number for 1918G. 1914G part was shown for both. Section 1, page 25 – Corrected Guide part numbers for Conventional 316SS & Conventional Monel. Section 1, p. 47 – 1912/14 Guide part number replaced, was 4068802. Section 4, p. 11 – 1912/14/16 Guide part number was 4740608. Section 4, p. 31, 35, 39, 43, 47, 51, 55, 59 – Replaced guide part numbers for Conventional and Bellows, all sizes. Listed former part in () . Section 4, p.30 – Spindle Assembly for 1905/06 P3 was 1985501. Section 4, p.57 – Adjusting ring pin part number was 1077715. Section 5b, p. 8 – Corrected typos on O-Ring Composite sheet, for all materials. Section 5a, p.8 – Base MNPT part numbers changed to be the assembly part numbers. Base FNPT part numbers corrected – were listed as Low Pressure part numbers. Section 7, p.3 – ½" and ¾" 1982, switched the Cap Gasket and Adj. Ring Pin gasket part numbers.

**Safety Relief Valve
Parts Reference Manual
REVISION SHEET**

Revisions made to this instruction are listed in detail and chronological order.

DATE	REV. NO.	DESCRIPTION
5/04/04	8	Section 1, page 20 – Corrected 316 SS Disc holder part numbers (LA) - were 4626702, 4626703, & 4626704. Section 5a, page 8 – Corrected Base MNPT, 316 SS part numbers were for all sizes.
9/13/04	9	Section 5a, page 4 – Corrected Spring Washer part numbers for all sizes.
9/23/04	10	Section 1, page 38 – Corrected Spindle part number 1914/1916. Was listed as 0379201.
1/15/05	11	Section 1, page 12 – Adjusting screw locknut (316 SS, -2,-4) was 1049703. Section 7, page 3 – Adjusting ring pin gasket for 1 ½" 1982 was 3620112. Section 11, page 5 – Screwed Base for 1" 1996 was 4602501.
5/23/06	12	Section 1, page 57 – Corrected spring washer for 1910T-4, was 0427301.
1/15/07	13	Section 1, page 9 – Spindle part number in 410 St. St. for 1914/16 (Bellows Design -2, -4) was 0333101. Section 11, page 4 – Disc holder for 1 ½" 1997 & 2" 1998 was 4465602.
11/13/07	14	Section 1, page 47 – Corrected base studs for 1905/6 P was 3262551
2/11/08	15	Section 1, Pages 12, 18, 22, and 26 – Corrected 416 SS Adjusting Screw part numbers 1085117 – was 1085101(obsolete) Section 4, Pages 8, 11, 15, and 19 – Corrected 416 SS Adjusting Screw part numbers 1085117 – was 1085101(obsolete)
8/13/08	16	Section 5a, Page 3 – Corrected 316SS Guide for 19110L, 19126L, and 19226L part numbers.
05/07/09	17	Section 4, Page 31 – Item 14: Guide "B" and "C" Design changed to 4647908 (4647907- Melonite Coating no longer available)